

Reference Documentation Permit To Work Document Suite

30 December 2010

CSE-PTW-03



DOCUMENT CONTROL

Document Details

Document Reference/Name:	CS-PTW-03 PTW Reference Documentation
Version Number:	V2.0
Documentation Status:	Approved
Document Owner:	Corporate PTW Committee
Document Approval:	Senior Plant Manager
Next Scheduled Review Date:	December 2011

Version History

Version Number	Date	Reason/Comments
1.00.01	30/01/04	First Consultation Draft – across sites
1.00.02	03/2004	Inclusion of site comments and approved for release
2.00.00	12/2010	Updated formatting for consistency

Acts & Regulations

- QLD – Workplace Health and Safety Act 1995
- QLD – Workplace Health and Safety Regulation 1997
- QLD – Electrical Safety Act 2002
- QLD – Electrical Safety Regulation 2002
- QLD – Radiation Safety Act 1999
- QLD – Radiation Safety Regulation 1999

Australian Standards

- AS 1200 – Pressure Equipment
- AS 1210 – Pressure Vessels
- AS 1319 – Safety Signs for the Occupational Environment
- AS 1657 – Fixed Platforms, Walkways, Stairways and Ladders – Design, Construction and Installation
- AS 1674.1 – Safety in Welding and Allied Processes – Fire Precautions
- AS 1674.2 – Safety in Welding and Allied Processes – Electrical
- AS 1680.1 – Interior Lighting Part 1: General Principles and Recommendations
- AS 1891.1 – Industrial Fall Arrest Systems and Devices – Safety Belts and Harnesses
- AS 1891.2 – Industrial Fall Arrest Systems and Devices – Static Lines
- AS 1891.3 – Industrial Fall Arrest Systems and Devices – Fall-arrest Devices
- AS 1891.4 – Industrial Fall Arrest Systems and Devices – Fall-arrest Systems and Devices – Selection, Use and Maintenance
- AS 1966.1 – Electric Arc Welding Power Sources – Transformer Type
- AS 1966.2 – Electric Arc Welding Power Sources – Rotary Type
- AS 1966.3 – Electric Arc Welding Power Sources – Plasma Arc Cutting and Welding Types
- AS 2177.1 – Non-Destructive Testing – Radiography of Welded Butt Joints in Metal
- AS 2243.4 – Safety in Laboratories – Part 4: Ionising Radiations
- AS 2381 – Electrical Installations for Explosive Atmospheres – Selection, Installation and Maintenance
- AS 2865 – Safe Working in a Confined Space
- AS 2927 – The Storage and Handling of Liquefied Chlorine Gas
- AS 3195 – Approval and Test Specification – Portable Machines for Electric Arc Welding and
- AS 3873 – Pressure Equipment – Operation and Maintenance
- AS 3998 – Non-Destructive Testing – Qualification and Certification of Personnel – General Engineering
- AS 4041 – Pressure Piping
- AS 4343 – Pressure Equipment – Hazard Levels
- AS 4360 – Risk Management
- AS 5601 – Gas Installations

Advisory Standards

- QLD – Advisory Standard – Welding (WTIA Health & Safety in Welding Technical Note Number 7)

QLD – Advisory Standard – Risk Management 2000

QLD – Advisory Standard – Plant 2000

QLD – Advisory Standard – Excavation 2000

Codes of Practice

QLD – Code of Practice – Working Near Exposed Live Parts 2002

QLD – Code of Practice – Electrical Work 2002

CS Energy - PTW Document Suite

PTW Manual

Mechanical Safety

Electrical Safety

JSEA

Confined Spaces

Hot Work

Working at Heights

Excavation

Radiation

CS Energy – Other Corporate Documents

Maintaining Electrical Installations Procedure

Maintenance of Electrical Safety Equipment and Clothing (PPE) Procedure

Barricading and Temporary Exclusion Procedure

External Documents

HVIA – High Voltage Isolation and Access Procedures

Queensland Electricity Generators Permit To Work Code of Practice

Site Specific Documents

Co-joined Boiler