

DOCUMENT CONTROL


Document Details

Document Reference/Name: PTW_Reference_Documentation_V1.00.02
 Version Number: V1.00.02
 Documentation Status: Approved
 Document Owner: Corporate PTW Committee
 Document Approval: Senior Plant Manager
 Next Scheduled Review Date: March 2005

Version History

Version Number	Date	Reason/Comments
0.00.01	30/01/04	First Consultation Draft – across sites
1.00.02	03/2004	Inclusion of site comments and approved for release.

PTW DOCUMENT SUITE



Acts & Regulations

QLD – Workplace Health and Safety Act 1995
QLD – Workplace Health and Safety Regulation 1997
QLD – Electrical Safety Act 2002
QLD – Electrical Safety Regulation 2002
QLD – Radiation Safety Act 1999
QLD – Radiation Safety Regulation 1999

Australian Standards

AS 1200 – Pressure Equipment
AS 1210 – Pressure Vessels
AS 1319 – Safety Signs for the Occupational Environment
AS 1657 – Fixed Platforms, Walkways, Stairways and Ladders – Design, Construction and Installation
AS 1674.1 – Safety in Welding and Allied Processes – Fire Precautions
AS 1674.2 – Safety in Welding and Allied Processes – Electrical
AS 1680.1 – Interior Lighting Part 1: General Principles and Recommendations
AS 1891.1 – Industrial Fall Arrest Systems and Devices – Safety Belts and Harnesses
AS 1891.2 – Industrial Fall Arrest Systems and Devices – Static Lines
AS 1891.3 – Industrial Fall Arrest Systems and Devices – Fall-arrest Devices
AS 1891.4 – Industrial Fall Arrest Systems and Devices – Fall-arrest Systems and Devices – Selection, Use and Maintenance
AS 1966.1 – Electric Arc Welding Power Sources – Transformer Type
AS 1966.2 – Electric Arc Welding Power Sources – Rotary Type
AS 1966.3 – Electric Arc Welding Power Sources – Plasma Arc Cutting and Welding Types
AS 2177.1 – Non-Destructive Testing – Radiography of Welded Butt Joints in Metal
AS 2243.4 – Safety in Laboratories – Part 4: Ionising Radiations
AS 2381 – Electrical Installations for Explosive Atmospheres – Selection, Installation and Maintenance
AS 2865 – Safe Working in a Confined Space
AS 2927 – The Storage and Handling of Liquefied Chlorine Gas
AS 3195 – Approval and Test Specification – Portable Machines for Electric Arc Welding and
AS 3873 – Pressure Equipment – Operation and Maintenance
AS 3998 – Non-Destructive Testing – Qualification and Certification of Personnel – General Engineering
AS 4041 – Pressure Piping
AS 4343 – Pressure Equipment – Hazard Levels
AS 4360 – Risk Management
AS 5601 – Gas Installations

Advisory Standards

QLD – Advisory Standard – Welding (WTIA Health & Safety in Welding Technical Note Number 7)
QLD – Advisory Standard – Risk Management 2000
QLD – Advisory Standard – Plant 2000
QLD – Advisory Standard – Excavation 2000

Codes of Practice

QLD – Code of Practice – Working Near Exposed Live Parts 2002
QLD – Code of Practice – Electrical Work 2002

CS Energy - PTW Document Suite

PTW Manual
Mechanical Safety
Electrical Safety
JSEA
Confined Spaces
Hot Work
Working at Heights
Excavation
Radiation

CS Energy – Other Corporate Documents

Maintaining Electrical Installations Procedure
Maintenance of Electrical Safety Equipment and Clothing (PPE) Procedure
Barricading and Temporary Exclusion Procedure

External Documents

HVIA – High Voltage Isolation and Access Procedures
Queensland Electricity Generators Permit To Work Code of Practice

Site Specific Documents

Co-joined Boilers